

Machine Protection - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|-------|---------|----------|----------|--|-----------------|---------------------|
| 19472 | Support | Closed | Normal | Changes to the frequency device. | Richard Neswold | 04/04/2018 10:28 AM |
| 19131 | Support | Closed | High | Add another ring pickup to the loss monitor task | Richard Neswold | 03/15/2018 03:38 PM |
| 19130 | Support | Closed | Normal | Finish PECL driver | Richard Neswold | 03/13/2018 02:03 PM |
| 12363 | Support | Closed | Normal | BLMs in SRFBLM front-end return [57 -77] | Richard Neswold | 04/20/2016 11:09 AM |
| 12140 | Support | Feedback | Low | Need to create a computed device for PXIMPS | Richard Neswold | 08/09/2018 04:00 PM |
| 12065 | Support | Closed | Normal | Rename devices in SRFMPS | Richard Neswold | 03/25/2016 02:30 PM |
| 11834 | Support | Closed | Normal | PXIMPS Processor board doesn't boot reliably. | Richard Neswold | 11/09/2017 10:54 AM |
| 11527 | Support | Closed | Normal | The V1495 card, used in PXIMPS, added registers | Richard Neswold | 01/28/2016 10:45 AM |